

MOVEABLE SHELVING PROJECT OBSERVATIONS AS OF 7-26-71

1. Bay 1, Sect. 2, Aisle 1 (aisle nearest motor) -- Secondary safety hits shelves before it hits base blocks.
2. Bay 2, Sect. 3 -- Anti-tipping device installed at least 2" from edge of shelves. It should be right on end of shelves except back 1" on end panel end.
3. Bay 1, Sect. 2, Aisle 1 -- Lower secondary safety too close to stationary base and needs to be secured to all base blocks.
4. Bay 1, Sect. 1, Aisle 2 -- Overhead arm extender bracket spacer loose. Also, the bolts need to be turned over.
5. Bay 1, Sect. 1 Stationary -- Not room for boxes because of wires. In fact, there is a serious design problem on all equipment and wires on top shelf for all of Bay 1 that will have to be resolved before work continues on next bays:

arm extender placement
excess wire in way of boxes
wires over edge of sharp metal

6. Bay 1, Sect. 2 Stationary -- 15" shelf needs end panel.

25X1A9a

C/Using Service

Distribution:

1 -
1 -
1 -
1 -
1 -
1 -
1 -

25X1A9a